

Appendix A – street scene photographs.

July 2015 – from east



September 2017 – from east



July 2015 – from north



September 2017 – from north



Appendix B – Stem viewed from front garden.

July 2015 – from east



September 2017 – from east



July 2015 – from southwest



September 2017 - from south west



July 2015 – from west



September 2017 – from west



Appendix C – Driveway adjacent to stem base – September 2017.




Appendix D – front garden wall.



View adjacent to wall looking east



minor cracking / loose mortar



View adjacent to wall looking west

